



GALAXY FLOORING

SPECIALISTS

SALES MAN: PETER MASHAMAITE
CELL: 0726442844/0659411980
EMAIL: PETERMASHAMAITE@GMAIL.COM
ADDRESS: 25 DRAKENSBERG ALRODE SOUTH
ALBERTON
WWW.SSSOLAR.CO.ZA/SALES@SSSOLAR.CO.ZA



Polyurethane Mapcoat PU 20 N Grey FLOORING

Where to use: New or existing substrates, preparing them to receive all kinds of flooring where a high resistance to loads and traffic required. It is for interior use only. Typical applications would include use in hospitals, hotels, theatres, schools and shopping centres.

- Epoxy Coatings
- Polyurethane Coatings
- Decorative Overlays
- Levelling Cement Screeds
- Decorative Epoxy & Polyurethane Screeds
- Terrazzo Systems
- Polyurethane Floor Screeds



Epoxy-floor-coatings-/POLYURETHANE/CEMENT

Call-auto fee R600 around Gauteng

Please note that these prices are approximate and may vary depending on factors such as surface preparation, material quality, labour costs,

Epoxy Flooring Type Price Range per Square Meter (in ZAR) Entry-Level 2mm and the specific requirements of your project. It is always a good idea to contact silver solutions 2492 for customized quotes to get the best deal for your epoxy/ Polyethylene flooring installation.





GALAXY FLOORING

SPECIALISTS

SALES MAN: PETER MASHAMAITE
CELL: 0726442844/0659411980
EMAIL: PETERMASHAMAITE@GMAIL.COM
ADDRESS: 25 DRAKENSBERG ALRODE SOUTH
ALBERTON
WWW.SSSOLAR.CO.ZA/SALES@SSSOLAR.CO.ZA



Surface preparation: Proper surface preparation is crucial for the longevity and performance of epoxy flooring. The cost of surface preparation depends on the current condition of the substrate and the necessary treatments, such as cleaning, repairing cracks, and grinding.

Material quality: The quality of the epoxy resin and hardener will affect the overall cost of the project. Higher-quality materials typically have a higher price tag but offer better performance and durability.

As a general rule, epoxy flooring price around R750-R1300 per square meter for two coats over a prepared concrete surface. The price can go up to R1500-R2000 per square meter when you pay for diamond grinding to prepare the concrete/ **self-levelling screed** followed by a decorative

Pretty much anywhere people go to splash out or shape up, tuck in or time out, our flooring solutions pave their way towards your places of commerce. Our range of coatings, screeds and overlay solutions deliver superb protection and offer customised decorative finishes to suit a variety of environments. We literally surface everywhere in the form of wood repair systems, anti-corrosion systems, floor and wall protective coatings, polyurethane and hygienic non-slip flooring, waterproofing, and even metal repair system.



Epoxy flooring is applied in two or more coats to the concrete surface. The first coat is a base coat that is applied to the surface to create a smooth and even base. The second coat is the colour coat that is applied to create the desired finish and design. The final coat is a clear topcoat that is applied to protect the surface and enhance its durability.

Benefits of Epoxy Flooring

Many companies chose epoxy flooring for its ease and strength. Epoxy flooring is the perfect solution for floors that must withstand extreme temperatures, foot and machine traffic, chemicals, oil, and other fluids without peeling or corroding over years of constant use. Food processing, electronics, pharmaceutical, meat and poultry, distilleries, dairy, industrial, and manufacturing facilities are just some of the industries for which epoxy flooring is the perfect solution.

Seamless, easily cleanable surface

Because epoxy is poured, there aren't seams, joints, or ridges like with tile or other types of flooring. This makes epoxy a more sanitary flooring option, eliminating cracks and crevices for dirt and bacteria to hide during cleanings. An anti-microbial additive can take the sanitation to another level for food plants or healthcare facilities. Also, its smooth surface makes it easier for hospital gurneys or forklifts to roll over without jostling or resistance from floor seam bumps.